



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2067

Work Order Type: Weatherization

Audit Name: 14014SO2067

CLIENT INFORMATION

Client Name:

Address:

Client ID: 14014SO2067

PETERSBURG, TN 37144

Alt. Client ID: LINCOLN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY

Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY

Fax: (931) 438-0074

FAYETTEVILLE, TN 37334-2001

Email Address: e.satterfield@schra.us

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 14014SO2067

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2067

Report Run On: 5/21/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 7

Measures

Measure 1 Infiltration Redctn				Components			Inspected		
Comment							<input type="checkbox"/>		
1. REDUCE INFILTRATION BY 6355 CFM'S / REPAIR LARGE HOLE AT WATER HEATER / REPAIR CEILING OF ROOM NEXT TO WATER HEATER CLOSET (11X15) APPROX. 165 SQ.FT. / SEAL AROUND B-VENT PIPE ON WATER HEATER / SEAL CHIMNEY / CASE OUT AND SEAL WHERE TRAILER WALL AND HOUSE WALL JOIN TO WATER HEATER 2. INSTALL WINDOW LOCK 3. PUSH UP SECOND WINDOW AND LATCH 4. W/S AND D/S BACK DOOR 5. INSTALL NEW STORM HARDWARE AND W/S AND D/S ON CARPORT DOOR 6. INSTALL NEW STORM HARDWARE AND W/S AND D/S ON FRONT DOOR 7. INSTALL (3) 11X14 ROOF VENTS									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Supplies	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Measure 2 Replace Htg. System**Components****Inspected****Comment** INSTALL VENTED HEATER WITH FAN - RUN NEW WIRE FROM
ELECTRIC BOX TO FAN☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	VENTED HEATER	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Measure 3 Window Replacement****Components****Inspected****Comment** REPLACE BROKEN STORMS☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window Replacement	Each	2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:**

Client Name:

Client ID: 14014SO2067

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2067

Report Run On: 5/21/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 7

Measure 4 DWH Pipe Insulation**Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 5 Attic Ins. R-19****Components****Inspected****Comment** BLOW UNDER ROOFED PART OF ATTIC - DENSE PACK☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-19	SqFt	2140					
2	Labor	LABOR	Hour						

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO2067

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2067

Report Run On: 5/21/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 7

Measure 6 DWH Tank Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 7 Window Sealing				Components				Inspected	
Comment CAULK ALL WINDOWS / SEAL AC									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Window Sealing	Each Window	15					
2	Labor	LABOR	Hour						
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 9 Fix Improper Venting (Clothes Dryer)				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Metal Flex	Each	1					
2	Labor	Labor	Hour	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 10 PressureRelief Piping Needed				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1					
2	Labor	Labor	Hour	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 11 Smoke Detector is Needed**Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke / Carbon detector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 14014SO2067

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2067

Report Run On: 5/21/2010

DOE Weatherization Assistant

Version 8.5.0

Page 7 of 7